


Cutometer Report

Printout: 3/16/2009 3:45:53 PM



Title:	Curve 1	Curve 3	Curve 2	Curve 1
First name:	Jerry	Jerry	Jerry	Jerry
Name:	Fortunato	Fortunato	Fortunato	Fortunato
Date:	1/31/2008	1/31/2008	1/31/2008	1/31/2008
Time:	4:34:	4:35:	4:35:	4:35:
Mode:	1	1	1	1
Repetitions:	20	20	20	20
Pressure:	450 mb	450 mb	450 mb	450 mb
T-on / T-off:	1.00 s 1.00 s	1.00 s 1.00 s	1.00 s 1.00 s	1.00 s 1.00 s
Temperature:	20 °C	20 °C	20 °C	20 °C
Air humidity:	50 %	50 %	50 %	50 %
Skin area:		Wrist3	Wrist2	Wrist1
Comment:				
R0	0.239	0.238	0.323	0.239
R1	0.067	0.052	0.065	0.067
R2	0.720	0.782	0.799	0.720
R3	0.315	0.296	0.375	0.315
R4	0.170	0.127	0.135	0.170
R5	0.687	0.811	0.650	0.687
R6	0.494	0.497	0.363	0.494
R7	0.460	0.542	0.477	0.460
R8	0.172	0.186	0.258	0.172
R9	0.076	0.058	0.052	0.076
F0	8.452	7.603	9.525	8.452
F1	0.021	0.020	0.033	0.021
F2	1.004	0.744	0.684	1.004
F3	6.542	7.391	10.249	6.542
F4	11.559	11.145	14.354	11.559